
# NA2-N SERIES General Purpose Area Sensor



# Flexible solutions for your on-site needs. High performance made easy.

The NA2-N series offers incredibly high performance in a general purpose area sensor.

The slim body, just 13mm thick and 30mm wide, can be installed almost anywhere, greatly increasing planning efficiency.

With a wide range of thin resin case type area sensors, from sensing height at 540mm (28 beam channels) down to 140mm (8 beam channels), you can choose the size that best suits your purpose.

In order to meet global market standards, these sensors conform to the CE marking EMC Directive and are currently undergoing UL Recognition certification. In addition to this, a PNP output type, which is in high demand in Europe, is also available.

This general purpose & slim body area sensor is the answer to all of your on-site needs.

\* The NA2-N series cannot be used as a safety sensor.

#### **ORDER GUIDE**

Appearance	Sensing range	Model No.	Number of beam channels	Sensing height (mm)	Output	
		NA2-N8	8	140	NPN open-collector transistor	
Beam channel No.	5m	NA2-N8-PN	0	140	PNP open-collector transistor	
		NA2-N12	12	220	NPN open-collector transistor	
		NA2-N12-PN			PNP open-collector transistor	
		NA2-N16	16	300	NPN open-collector transistor	
Sensing height		NA2-N16-PN			PNP open-collector transistor	
		NA2-N20	20	380	NPN open-collector transistor	
		NA2-N20-PN			PNP open-collector transistor	
2 Beam pitch 1 120mm		NA2-N24		400	NPN open-collector transistor	
		NA2-N24-PN	24	460	PNP open-collector transistor	
		NA2-N28	00	540	NPN open-collector transistor	
		NA2-N28-PN	28	540	PNP open-collector transistor	

#### **OPTIONS**

Designation	Model No.	Description				
OS-NA2-N8 For 8 beam chan		For 8 beam channels				
	OS-NA2-N12	For 12 beam channels	The slit mask restrains the amount of			
Slit mask	OS-NA2-N16	For 16 beam channels	beam emitted or received. (seal type, 10 Nos. set)			
Silt mask	OS-NA2-N20	For 20 beam channels	Sensing range: 4m (slit on one side)			
	OS-NA2-N24	For 24 beam channels	1.5m (slit on both sides)			
	OS-NA2-N28	For 28 beam channels				
Sensor mounting	MS-NA1-1	Four bracket set Eight M4 (length 18mm) screws with washers (Four screws with washers are used), eight nuts, four hooks, four spacers				
bracket (Note) MS-NA2-1		and four M4 (length 15mm) screws with washers are attached.  [Spacers are not attached with MS-NA1-1. M4 (length 15mm)] screws with washers are not used for NA2-N series.				
	MS-NA3-N8	For 8 beam channels				
	MS-NA3-N12	For 12 beam channels	Supports the body of the sensor when			
Sensor supporting	MS-NA3-N16	For 16 beam channels	used in an environment with strong vi			
bracket	MS-NA3-N20	For 20 beam channels	bration.			
	MS-NA3-N24	For 24 beam channels	Two bracket set			
	MS-NA3-N28	For 28 beam channels				

Note: Do not fix the sensor mounting bracket on the front surface of the sensor.


#### Slit mask

The slit mask restricts the amount of beam emitted or received and is used to reduce interference be-

the is used to reduce interference between neighboring sensors.

It is also used if the light is so strong that it passes through the object.

Remove the cover (metal plate) from the front of the sensor and replace it with the slit mask.
The sensing range is reduced when the slit mask is used.



#### Sensor mounting bracket

· MS-NA1-1

· MS-NA2-1








M4 screws with washers, nuts, and hooks are attached.

M4 screws with washers, nuts, hooks and spacers are

#### Sensor supporting bracket



#### Sensor protection bracket

Sensor protection brackets are available to protect the front and sides of NA2-N12(-PN), NA2-N16(-PN) and NA2-N20(-PN). Please contact our office for further details.

# NA2-N

#### **SPECIFICATIONS**

Sensing height   Sensing range   Beam pitch   Sensing object   Supply voltage   Supply voltage   Job indicator ON   Job indicator OFF   Short-circuit protection   Response time   Emitter   Emitter   Emitter   Supply Interference prevention function   Test-run function   Pollution degree   Pollution	Applied voltag     Residual volta      Emitting indicator:	0.8W or less 0.7W or less 0.8W or less 0.7W	#30mm or mo #30mm or less #30.9W	1.0W or less 0.9W or less 1.0W or less 0.9W or less  PNP output type> PNP open-collector Maxmum sourc Applied voltage Residual voltage Procedure or DC-13 When one or more bear	1.1W or less 1.0W or less 1.1W or less 1.0W or less (at 100m or less) 1.0W or less	mA source current) mA source current)
Sensing height  Sensing range  Beam pitch  Sensing object  Supply voltage  Job indicator ON  Job indicator OFF  Job indicator OFF  Job indicator OFF  Output  Utilization category  Output operation  Short-circuit protection  Response time  Emitter  Sopro Job Indicator OFF  Interference prevention function  Test-run function	0.7W or less 0.6W or less 0.6W or less 0.6W or less  NPN output type NPN open-collected Maximum sind Applied voltag Residual voltag Emitting indicator:	0.8W or less 0.7W or less 0.8W or less 0.8W or less 0.7W or less 0.7W or less or transistor k current: 100mA le: 30V DC or less (bet age: 1V or less (at 100 0.4V or less (at 16)  ON when all beam  10ms or less (12) Green LED × 2 (light Frequency B setting)	300mm  5 20  \$30mm or mo 12 to 24V DC±10%  0.9W or less  0.8W or less  0.9W or less  0.8W or less  0.8W or less  tween output and 0V) mA sink current) mA sink current) mB sink current  Incorp	380mm  mm  re opaque object  Ripple P-P 10% or less  1.0W or less  0.9W or less  1.0W or less  O.9W or less  PNP output type> PNP open-collector Maxmum sourc Applied voltage Residual voltage r DC-13  when one or more bear	460mm  1.1W or less 1.0W or less 1.0W or less 1.0W or less 1.0W or less 2.0V or less (at 100mA) 2.30V DC or less (betwee: 1V or less (at 100mO).4V or less (at 16mo) 2.4W or less (at 16mo) 2.4W or less (at 16mo) 3.4W or less (at 16mo) 4.4W or less (at 16mo) 4.4W or less (at 16mo) 5.4W or less (at 16mo) 6.4W or less (at 1	1.2W or less 1.1W or less 1.2W or less 1.1W or less 1.1W or less veen output and +V) MA source current) MA source current)
Sensing range  Beam pitch  Sensing object  Supply voltage  Job indicator ON  Job indicator ON  Job indicator OFF  Output  Utilization category  Output operation  Short-circuit protection  Response time  Emitter  Peceiver  Interference prevention function  Test-run function	0.7W or less 0.6W or less 0.7W or less 0.6W or less					


Note: Obtain the current consumption from the following equation.

Current consumption=Power consumption÷Supply voltage (e.g.) In case of NA2-N8 (when job indicator lights on)
When the supply voltage is 12V, the current consumption of the emitter is: 0.7W÷12V=0.058A=58mA.

#### I/O CIRCUIT AND WIRING DIAGRAMS

#### NPN output type

#### I/O circuit diagram



Internal circuit ← o → Users' circuit

- Notes: 1) Input (pink) is the job indicator input when No.4 of the operation mode switch on the emitter is set to the OFF side, and it is the test input when the switch is set to the ON side.
  - In order to use the job indicator as a large operation indicator, connect the input (pink) of the emitter to the output (black) of the receiver.
  - 3) When the test input is set, the job indicator does not light up or blink.


Symbols ... D1: Reverse supply polarity protection diode


D<sub>2</sub>: Reverse current protection diode Z<sub>D</sub>: Surge absorption zener diode

Zp: Surge absorption zener dioc Tr: NPN output transistor

E : Job indicator

#### Wiring diagram






Note: Refer to **PRECAUTIONS FOR PROPER USE** (P.7~) for job indicator operation or test input operation.

#### PNP output type

#### I/O circuit diagram



Notes: 1) Input (pink) is the job indicator input when No.4 of the operation mode switch on the emitter is set to the OFF side, and it is the test input when the switch is set to the ON side.


In order to use the job indicator as a large operation indicator, connect the input (pink) of the emitter to the output (black) of the receiver.


3) When the test input is set, the job indicator does not light up or blink.

Symbols ... D1: Reverse supply polarity protection diode
D2: Reverse current protection diode
ZD: Surge absorption zener diode
Tr: PNP output transistor

E : Job indicator

#### Wiring diagram






Note: Refer to **PRECAUTIONS FOR PROPER USE** (P.7~) for job indicator operation or test input operation.


## NA2-N

#### **SENSING CHARACTERISTICS (TYPICAL)**


### Correlation between setting distance and excess gain



#### Parallel deviation (All models)



#### Angular deviation (All models)




#### PRECAUTIONS FOR PROPER USE



- This sensor is not for press machine safeguard. Do not use this sensor for any press machine.
- This product is not a safety sensor. Its use is not intended or designed to protect life and prevent body injury or property damage from dangerous parts of machinery. It is a normal object detection sensor.
- Area sensors conforming to safety standards are available.
- For details, please contact our office.

#### **Functional description**




		Description	Function				
	1	Emission frequency selection switch	1 == :Frequency A	A 1 ■ :Frequency B			
	2	Job indicator	Lights up wl 2 = : the job indic input is Low	ator 2 📼 : the job indicator			
tter	3	mode switch	3 == :Lighting	3 ■ :Blinking			
Emitter	4	Job indicator/ Test-run selection switch	4 == :Job indicator	r input 4 💶 :Test input			
	(5)	Job indicator (Red LED)	Lights up, blinks or lights off when the job indicato input is applied, selected by operation mode switch.				
	6	Emitting indicator (Green LED×2)	Light up during emission; one LED lig for Frequency A setting, both LEDs lig for Frequency B setting.				
	7	Job indicator (Red LED)	0 17	lights off when the job indicator cted by operation mode switch.			
Receiver	Stable incident beam indicator (Green LED)		Lights up when all beams are stably received.	When an excess current flows through the out- put, the stable incident beam indicator and the			
T.	9	Operation indicator (Red LED)	Lights up when one or more beams are interrupted.	operation indicator on the receiver blink simul- taneously due to the op- eration of the short-cir- cuit protection circuit.			

#### Mounting

 Use M4 screws with washers and M4 nuts. The tightening torque should be 0.5N·m or less. During mounting, do not apply any bending or twisting force to the sensor.

Please arrange the screws and nuts separately.



#### Job indicator operation selection

The operation of the job indicator can be selected with job indicator mode switch.

Job indicator	Job indicator operation			
mode switch	Job indicator input: Low	Job indicator input: High		
1 2 3	Lights up	Lights off		
1 2 3	Lights off	Lights up		
1 2 3	Lights up	Blinks		
1 2 3 4	Lights off	Blinks		

#### Job indicator input signal condition

Output	Signal	Signal condition
·····	Low	0 to 2V
NPN output	High	5 to 30V, or open (Note)
DNDtt	Low	0 to 2V, or open (Note)
PNP output	High	8V to +V

Note: Insulate the wire if it is kept open.

#### PRECAUTIONS FOR PROPER USE

#### To use job indicator as large operation indicator


 The job indicators can be used as large operation indicators by setting No.4 of the operation mode switch to the OFF side and connecting the input (pink) of the emitter to the output (black) of the receiver.

Job indicator mode switch	Light state	Dark state
1 2 3 4	Lights up	Lights off
1 2 3 4	Lights off	Lights up
1 2 3 4	Lights up	Blinks
1 2 3 4 -	Light off	Blinks

Note: In order to use the job indicators as large operation indicators, make sure to set No.4 of the operation mode switch to the OFF side. If it is set to the ON side, the job indicator does not light up or blink.

#### Orientation

• The emitter and the receiver must face each other correctly. If they are set upside down, the sensor does not work.






 The emission is stopped when No.4 of the operation mode switch is set to the ON side and the input (pink) of the emitter is made High (PNP output type: Low).

Since the output can be turned ON/OFF without the sensing object, this function is useful for start-up inspection. If the output follows the application/withdrawal of the test input, the sensor operation is normal, else it is abnormal.

#### Operation mode switch setting

OFF	ON
1 2 3 4	1 2 3 4

#### Time chart




Notes: 1) When the test-run function is set, the job indicator (red) does not light up or blink.

When emission is stopped during the test-run function, the emitter's emitting indicator (green) does not light up.

#### Interference prevention function

By setting different emission frequencies, two units of NA2-N series can be mounted close together, as shown in the figure below. The emission frequency can be checked by the number of LEDs lighting up in the emitting indicator on the emitter.



Sensor (E

#### Wiring

- Make sure to carry out the wiring in the power supply off condition.
- Verify that the supply voltage variation is within the rating.
- If power is supplied from a commercial switching regulator, ensure that the frame ground (F.G.) terminal of the power supply is connected to an actual ground.
- In case noise generating equipment (switching regulator, inverter motor, etc.) is used in the vicinity of this sensor, connect the frame ground. (F.G.) terminal of the equipment to an actual ground.
- Do not run the wires together with high-voltage lines or power lines or put them in the same raceway. This can cause malfunction due to induction.

#### **Others**


- Do not use during the initial transient time (500ms) after the power supply is switched on.
- · Avoid dust, dirt and steam.
- Take care that the sensor does not come in direct contact with water, oil, grease, or organic solvents, such as, thinner, etc.
- Take care that the sensor is not directly exposed to fluorescent light from a rapid-starter lamp or a high frequency lighting device, as it may affect the sensing performance.

# NA2-N

#### **DIMENSIONS (Unit: mm)**

#### NA2-N□ NA2-N□-PN

Sensor



2-\phi 4.6 supplementary 2-M4 nut seats 1.1 deep

Job indicator (Red)
Stable incident beam indicator (Green)
Job indicator (Red)

Job indicator (Red)

Model No. A B

С D В Α NA2-N8 (-PN) 140 180 52 190 Receiver NA2-N12 (-PN) 260 84 220 270 NA2-N16 (-PN) 124 300 340 350 164 NA2-N20 (-PN) 380 420 430 NA2-N24 (-PN) 204 460 500 510

540

590 244


580

NA2-N28 (-PN)

Note: Located on the right side in case of NA2-N8 (-PN).

#### MS-NA1-1 Sensor mounting

Sensor mounting bracket (Optional)



Material: Cold rolled carbon steel (SPCC) (Uni-chrome plated)

Four bracket set


Eight M4 (length 18mm) screws with washers (Four screws with washers are used),

eight nuts, four hooks and four M4 (length 15mm) screws with washers are attached.

M4 (length 15mm) screws with washers are not used for NA2-N series.

#### **Assembly dimensions**

Mounting drawing with the receiver




Model No.	Α	В	O	D	E
NA2-N8 (-PN)	140	180	190	52	160
NA2-N12 (-PN)	220	260	270	84	240
NA2-N16 (-PN)	300	340	350	124	320
NA2-N20 (-PN)	380	420	430	164	400
NA2-N24 (-PN)	460	500	510	204	480
NA2-N28 (-PN)	540	580	590	244	560



#### **DIMENSIONS (Unit: mm)**

#### **MS-NA2-1**

Sensor mounting bracket (Optional)



Material: Cold rolled carbon steel (SPCC) (Uni-chrome plated)


Four bracket set

Eight M4 (length 18mm) screws with washers (Four screws with washers are used), eight nuts, four hooks, four spacers and four M4 (length 15mm) screws with washers are attached.

M4 (length 15mm) screws with washers are not used for NA2-N series.

#### **Assembly dimensions**

Mounting drawing with the receiver




Model No.	Α	С	D	F
NA2-N8 (-PN)	140	190	52	130
NA2-N12 (-PN)	220	270	84	210
NA2-N16 (-PN)	300	350	124	290
NA2-N20 (-PN)	380	430	164	370
NA2-N24 (-PN)	460	510	204	450
NA2-N28 (-PN)	540	590	244	530

#### MS-NA3-N□

Sensor supporting bracket (Optional)

#### **Assembly dimensions**


Mounting drawing with the receiver



Note: The sensor supporting bracket can be used for both the emitter and the receiver.

Material: Aluminum (Black ALMITE)

Two bracket set



Model No.	Α	В	G	Н	J	K
MS-NA3-N8	140	180	194	118	170	38
MS-NA3-N12	220	260	274	102	250	86
MS-NA3-N16	300	340	354	102	330	126
MS-NA3-N20	380	420	434	102	410	166
MS-NA3-N24	460	500	514	102	490	206
MS-NA3-N28	540	580	594	102	570	246

#### **DIMENSIONS (Unit: mm)**